

State of Utah

Department of Natural Resources

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director Permitee: WEST RIDGE RESOURCES Operator: WEST RIDGE RESOURCES

Site: WEST RIDGE MINE

Representatives Present During the Inspection:

David Shaver Manager

Pete Hess Environmental Scientist III

Address: PO BOX 1077, PRICE UT 84501

County: CARBON

GARY R. HERBERT Lieutenant Governor

Company

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Inspection Report JON M. HUNTSMAN, JR. Governor

Permit Number:	C0070041		
Inspection Type:	COMPLETE		
Inspection Date:	Wednesday, October 31, 2007 10/31/2007 8:48:00 AM		
Start Date/Time:			
End Date/Time:	10/31/2007		
Last Inspection:	Monday, September 24, 2007		

Inspector: Pete Hess, Environmental Scientist III

Weather: Clear, cool; 40's F. InspectionID Report Number: 1452

Accepted by: dhaddock

11/26/2007

Current Ac	reages
------------	--------

6,114.89	Total Permitted		
29.06	Total Disturbed		
	Phase I		
	Phase II		
	Phase III		

Mineral Ownership

Types of Operations ✓ Federal ✓ Underground ✓ State ☐ Surface Loadout County Processing Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The Permittee is current relative to the required electronic quarterly submittal of surface and ground water monitoring information.

There are no pending compliance actions at this site.

Inspector's Signature:

Pete Hess, Environmental Scientist III

Date

Friday, November 23, 2007

Inspector ID Number: 46

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801 telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov Permit Number: C0070041 Inspection Type: COMPLETE

Inspection Date: Wednesday, October 31, 2007

Page 2 of 4

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	~		✓	
2.	Signs and Markers	V			
3.	Topsoil	V			
4.a	Hydrologic Balance: Diversions	✓			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	V		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures	✓		V	
4.d	Hydrologic Balance: Water Monitoring	✓			
4.e	Hydrologic Balance: Effluent Limitations	✓		✓	
5.	Explosives	✓			
6.	Disposal of Excess Spoil, Fills, Benches		V		
7.	Coal Mine Waste, Refuse Piles, Impoundments		✓		
8.	Noncoal Waste	V			
9.	Protection of Fish, Wildlife and Related Environmental Issues	✓		V	
10.	Slides and Other Damage		✓		
11.			✓		
12.	Backfilling And Grading		✓		
13.	Revegetation		✓		
14.	Subsidence Control	V		✓	
15.	Cessation of Operations		. 🗸		
16.2	Roads: Construction, Maintenance, Surfacing	V			
	Property of the Controls of the Control of the	✓			
17.	Other Transportation Facilities	V			
18.	Support Facilities, Utility Installations	V			
19.	AVS Check	V		✓	
20.	Air Quality Permit	V			
	Bonding and Insurance	✓		<u> </u>	
	Other				

Permit Number: C0070041
Inspection Type: COMPLETE

Inspection Date: Wednesday, October 31, 2007

Page 3 of 4

1. Permits, Change, Transfer, Renewal, Sale

The current State permit issued by the Division remains in effect until April 1, 2009. The Permittee has been asked to update the reclamation agreement for this site relative to the responsible individuals listed on the specific items / definition page of the agreement. Also the signatory authorities page should be updated. The signature shown on the affadavit of qualification page of this document is also outdated. The UPDES permit for this site was recently modified by the Utah Division of Water Quality to re-located the mine water discharge outfall within that document. Same is now extended through April 30, 2011. The current Air Quality approval order for this site was approved on January 14, 1999.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The third quarter of 2007 sediment pond inspection for the dual cell treatment facility was conducted by Mr. Dave Shaver on September 20, 2007. There were no hazardous conditions observed on that day, or during today's inspection.

4.c Hydrologic Balance: Other Sediment Control Measures

The Permittee is now treating the mine water which is discharged to UPDES outfall 002 for the high iron parameter. Recent results are encouraging with the results below the required maximum mandated within the DWQ permit. All flocculation is being done underground prior to the mine water reaching the surface.

4.e Hydrologic Balance: Effluent Limitations

Refer to comment under 4.c.

9. Protection of Fish, Wildlife and Related Environmental Issues

As noted under 4.c, the mine water now being discharged is below the DWQ effluent parameter level for total iron. There has not been any effect observed in the "C" Canyon channel below the Mine site relative to fish or wildlife.

14. Subsidence Control

The flyover which is conducted for subsidence monitoring at the West Ridge site was done during the month of September. Mr. Shaver stated that the results of that flyover were in the mail soon to be delivered. A meeting was held on October 25, 2007 to discuss the continuation of subsidence monitoring at the Grassy Trail Dam, which is adjacent to the now mined out Panel #7 at the West Ridge Mine. Individuals attending the meeting included representatives from West Ridge Resources, Inc., the Utah Division of Dam Safety, RB&G Engineering, DOGM, and the Mayors of both Sunnyside City and East Carbon City. The outcome of the meeting established the following; the frequency of the current monitoring regime would be continued. Also, the standard operating procedure and emergency action plan documents will be updated / modified to encompass transfer of notification responsibilities from specific individuals to generic key government officials relative to these two documents.

Inspection Continuation Sheet

Permit Number: C0070041
Inspection Type: COMPLETE

Inspection Date: Wednesday, October 31, 2007

Page 4 of 4

19. AVS Check

New ownership and control information for the West Ridge Resources site was approved by the Division on August 27, 2007, (Task ID #2838).

21. Bonding and Insurance

The current general liability insurance remains in effect through June 1, 2008. The current amount of the reclamation bond is listed as \$ 2,117,000.